

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Item	Volume	Issue #	Page #
1928 Royal Tour Car - Sale in Oxford	27	2	5
29 vs. 28 (Bult)	22	2	8
29 Roadster in front of ACD Office / Museum	24	1	9
29 Roadster's Vinyl Poster (McGee)	24	1	9
29 Roadster - Carb Fire (in July 2012)	26	3	3
29 Roadster - Carb Fire Update (Dec. 2012)	26	4	2
29 Roadster - Carb Fire Update (Mar. 2013)	27	1	3
55X Restoration ?'s (Don Mayton)	23	3	10
55X Restoration Team (Don Mayton)	24	1	4
Accelerator Position	7	1	8
Accessories	11	2	5
Accessories	14	4	7
Accessory Equipment	8	3	13
Accessory Light Wiring to Headlights	15	1	7
Accessory Heater - Francisco Article	26	1	6
Additives	11	4	8
Ads - Australian - Pt. 1	17	3	9
Ads - Searching for Vintage Ad website	25	1	10
Air Cleaner Improvement	8	1	10
Air Cleaner / filter Insert (Ed Lappin)	16	3	7
Air Cleaner - Motorcycle Replacement / Insert	20	4	6
Air Filter Decal	16	3	9
Air Filter replacement - Modern (Dean Tryon)	24	1	5
Allentown Meet (Bulgari)	30	3	1
Alternator - Fitting Modern (in P-to-P article)	24	1	3
Ambulance - Australian Story	19	1	8
Andersen Windows Car Article	15	1	3
Andersen Windows Car Article	23	3	3
Andersen Window Car - Photo (Thille)	23	4	9
Announcement Booklet	15	3	1
Announcement Booklet	15	4	7
Announcement Booklet	16	1	5
Announcement Booklet	16	2	5
Announcement - Pictures	18	3	4
Announcement - Pictures	18	4	5
Announcement - Pictures	19	1	2
Antique Auto Fasteners Address	19	2	11
Air Mixture Screw Adj. / Rod	8	3	12
Antifreeze - Pros & Cons	5	1	9
Antifreeze Mixture / type	5	3	10
Antifreeze - Type (Oat vs IAT)	25	1	10
Antifreeze - Texaco	25	2	8
Antifreeze - CarQuest	26	1	10
Arentine Hearse Story	29	4	3
Arm Rest Wood	12	2	12
Ashtray - 29-25 ?	20	3	13
Ashtray - Also see "Smoking Case"			
Astor Auto Show Price List	21	1	7
Astor Auto Show Location	21	2	10
Australian Holden Story - Part 1	15	3	6

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Australian Holden Story - Part 2	15	4	8
Australian - Gov. Min. in Limo	18	4	10
Australian Gov. Min.'s Limo - Current Owner	23	4	8
Australian National Meet - 2014 - Pre Going	28	3	3
Australian - Production	19	3	9
Australian Trip - Part 1 (2007)	21	2	2
Australian Trip - Part 2 (2007)	21	4	4
Australian Trip (WA) - 2014	28	4	4
Australian - Tracing 29-25X	21	3	7
Axle Nut Rear Wheel	13	2	9
Axle Ratios	9	1	6
Axle - Rear Oil Seal	10	4	14
Axle - Rear Problem ?	25	2	11
Axle - Rear Removal (Mayton)	25	4	5
Axle & Diff. Bearing Pre-Load Info	24	3	8
Bakelite (Steering Wheel Plastic) Refurb.	22	1	4
Bali - Touring Car Picture	27	4	10
Baseball - Buick Majors Team (1929)	28	1	7
Bathtub by Buick & Sherwood Mfg. Co.	29	1	12
Battery Installation	13	4	12
Battery Replacement	13	3	9
Battery - Info	18	2	5
Battery - Safe Charging Practices	18	4	8
Battery Hold-Downs	26	4	10
BCA Newsletter Award	19	4	1
BCA Newsletter Award	21	1	2
BCA Bugle Cover - Tony Bult's 29-55 & Shop	30	4	11
BCA Bugle Cover - Doug Jones' 29-44 (Nov. 87)	30	4	12
BCA Bugle Cover - Bob Jone's 29-44 (June 1974)	30	4	12
Bearings - Rear End	3	3	8
Bearings - Transmission	3	3	8
Belzona Products (Vyskocil)	30	2	7
Benson Update (Burridge)	26	2	1
Benson Update (Burridge)	27	2	2
Benson is Back (Brian Shields)	30	1	1
Benson - Pre 'The Rally of the Incas' (Brian Sheilds)	30	4	1
Berlin Assembly Plant	12	1	11
Bicknell, Bill's first car (29 Sedan)	27	1	10
Billboard in NZ (Phil Green)	28	3	1
Black Engines ?	25	1	11
Black Engines (Blair)	25	2	11
Block Cleaning	22	1	4
Block Crack Repair	7	2	11
Block Crack Repair	8	2	11
Block-Head Bolt Thread repair	6	2	9
Block - Fixing Cracks Behind Push Rods ?	30	1	7
Body -54CC - Who Built	4	1	12
Body Bolt - Model 54CC	9	4	12
Body - Underside - Colour ?	20	4	12
Body Nails	6	4	11
Body Parts - Proper Names	12	1	11
Body Sides Under Fender Colour	26	1	10
Body - Wood Types	6	1	13

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Body in Crate (1918 Buick)	26	2	10
Bodywork - British Ad	28	3	9
Bolt - Removal	18	2	5
Bovery Heater (Accessory) Article	26	2	7
Bow-Tie Use before 1929	17	2	10
Brashares Family Foundation Award (to WEM)	27	4	5
Brazil - My trip 2016 and lunch w/Julio Albermaz	30	1	2
Brazil - Dr. Marcos Meduri's 29-50L	30	3	5
Brake Adjustment Tip (Tryon)	25	1	9
Brake Conversion to Hydraulic (VG) Part 1	28	3	6
Brake Conversion to Hydraulic (VG) Part 2	28	4	9
Brake Conversion to Hydraulic (VG) Part 3	29	1	7
Brake Conversion to Hydraulic (VG) Part 4	29	2	8
Brake Drum - Adapting 1918 (Vaughn Gunthorpe)	23	3	8
Brake Lining	14	1	11
Break Lining - 1 or 2 Pieces	18	2	11
Brake Lining Supplier	14	4	6
Brake Lining Supplier	20	4	5
Brake Parts - Paint ?	8	1	11
Brake Reinstallation	14	2	4
Brake Rod Spring-Rear	5	1	7
Brake Rounding Tool ?	16	4	12
Brakes - Set-up (Fred Rawling)	29	2	7
Brake - 4 Wheel Triangle on 29 in McL- Buick Lit.	23	4	9
Brake - 4 Wheel Triangle on 29 McL- Buick (Norway)	27	3	5
Brake Temperatures ? (Tryon)	23	4	12
Brake Temperatures (Tryon)	24	1	12
Brake Adjustment Idea (Dean Tryon)	30	4	10
Bugs - Removal	23	1	8
Bugle Cover from Oct. 1982	21	4	10
Bugle Cover from July 1972 (Auber / Bult / Keiser)	24	2	10
Buick - Admin. Build. Pic. In 1929	17	3	13
Buick Club for Californians (Helen Hutchings)	28	2	10
Buick Collector's Club of America (Part 1)	27	1	9
Buick Collector's Club of America (Part 2)	27	2	9
Buick Collector's Club of America (Part 3)	27	3	6
Buick Collector's Club of America (Part 4 - Follow-up)	27	4	9
Buick Collector's Club of America (Part 5 - Follow-up)	28	2	10
Buick Emblems - Pt. 1	16	2	6
Buick Emblems - Pt. 2	16	3	5
Brake-Emergency	4	2	11
Brake - Front - Clevis Pins	19	2	11
Brake Reline Info (Tryon)	24	2	11
Brakes - Removing ?	24	3	12
Brazilian Roadster with Beauty Queen	26	2	9
Brazilian Roadster w/Beauty Queen and Bright Bumper	30	2	9
Bridge Score Card	14	4	18
Buehrig, Gordon & our 29 Buicks	21	4	9
Buick Derby - Sales Contest	25	2	5
Buick Factory Pics (Start) - Dan Bower	26	4	3
Buick Factory Pics (Part 2) - Dan Bower	27	1	5
Buick Factory Pics (Part 3) - Dan Bower	27	2	6
Buick Factory Pics (Part 4) - Dan Bower	27	3	3

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Buick Factory Pics (Part 5) - Dan Bower	27	4	8
Buick Factory Pics (Part 6) - Dan Bower	28	1	5
Buick Factory Pics (Part 7) - Dan Bower	28	2	3
Buick Picture	13	4	3,4,10
Buick Pictures	13	2	10,11
Buick Pictures	13	3	3,11,12,13
Buick Pricing - Start	17	4	5
Buick Bodies (W. F. Stewart)	16	2	3
Buick (29) vs. Chevrolet (48)	13	1	3
Buick's 100 th - Part 1	17	3	2
Bulgaria Race Driver (Dimitar Sokoloff) in Roadster	30	1	1
Bult - Group Photo of Eight 1929 Buicks	29	4	1
Bumper - Drooping	7	2	8
Bumpers for Exported Cars	12	1	13
Bumpers for Exported Cars	12	2	12
Bumper Bolt Installation	20	2	7
Bumper - 2 Bar	2	3	12
Bumper - 2 Bar	2	4	10
Bumper - 2 Bar (Picture)	15	1	9
Bumper - 2 Bar - USA (Picture)	20	1	7
Bumper - 2 Bar in Australia	15	3	12
Bumpers - 1930 ?	16	3	11
Bumper - Rear Split - Correct Bumperette Install.	26	2	6
Bumper - Rear - Homemade	19	3	9
Bumper - Rear - Strange Config. - for Trunk (?)	29	4	10
Bushings - Front and Rear Spring	3	3	8
Calendar - 29 Buick	11	1	12
Cam - Servicing Tip	10	3	14
Cam Gear Sizes ?	24	1	13
Cam Gear Sizes	24	2	12
Cam Gear Problems (Bill McLaughlin)	30	4	1
Camguard Additive	22	2	11
Camshaft Welding - Supplier	20	1	11
Cam Gear - Breakage	20	4	6
Car Cover - ?	15	2	12
Car Forwarding - Picture	19	4	9
Car Show Information Boards ?	29	4	9
Carb. - 28 Brass Bowl option	21	1	12
Carb. Adjustment Warning (Brent Bloede)	23	3	7
Carb Repair / Adjustment - Part 1	25	4	6
Carb Repair / Adjustment - Part 2	26	1	4
Carb. Bowl - Same for M & S	19	1	10
Carb. - Die-cast change over in Late 28	21	1	6
Carb Cover - Aluminum ?	24	3	12
Carb. (S / M) Differences	19	2	11
Carb. Cast Iron Pieces (S & M) - Discussion	19	1	10
Carb. Cast Iron Pieces (S & M) - Discussion	25	1	10
Carb. Cast Iron Pieces (S & M) - Discussion	25	2	9
Carb. - Drawing (116)	19	2	7
Carb. - Downdraft ?	19	4	13
Carb - Downdraft ? (What one to use)	24	4	13
Carb. - Downdraft Replacement - Use Marvel	23	1	10
Carb. - Downdraft Replacement	25	1	12

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Carb - Jet Specifications ?	18	3	13
Carb - Jet Tip Diam. ?	21	1	12
Carb Jet - Low Speed Packing / Gasket	24	1	12
Carb Jet - Low Speed Packing / Gasket	24	2	12
Carb - Use of Brass Bowl type Carbs - ?	15	1	11
Carb - Use of Brass Bowl type Carbs - ?	15	2	13
Carb. - Brass Bowl	18	4	11
Carb. - Brass Bowl	19	1	10
Carb. - Brass / Die Cast info	21	2	8
Carb. - 1928 Die Cast Bowl Gaskets	25	3	12
Carb - Switch to Zenith Marine	15	1	8
Carb - Switch to Zenith Marine	15	2	5
Carb - Updraft Switch - Supplier	20	2	12
Carb - Shut-off Valve (Don Mayton)	30	3	9
Carb Switch to Updraft - Ed Lappin	24	1	8
Carb Heat Riser Question	13	1	7
Carb Heat Riser Tube	18	1	5
Carburetor Info	12	4	12
Carb - Marvel Manual On-Line	18	3	6
Carb - Marvel Restoration Article (Part 1)	25	4	6
Carb - Marvel Restoration Article (Part 2)	26	1	4
Carb - Marvel Restoration Article (Part 3)	26	2	5
Carb - Marvel Restoration Article (Addendum)	26	3	7
Carb. - 116 Drawing / Dimensions	18	4	7
Carb. Problem ? (Clarke)	26	2	10
Carb. - Problems / Solutions	18	4	7
Carb. Problem Solved	19	3	11
Carburetor Float Coating	7	3	11
Carb Float Varnish Problem	15	1	8
Carb. Float Problem	20	3	13
Carburetor Jet Thread Size	3	4	8
Carburetor Jet Thread Size	5	2	12
Carburetor Jet Thread Size Clarification	5	3	11
Carb. Jet - Low Speed Packing / Gasket ? (Bult)	23	4	11
Carburetor Overhaul - Part 1	6	2	10
Carburetor Overhaul - Part 2	6	3	8
Carburetor Preheat Unit Info	6	2	8
Carburetor - Air Sucking Problem	5	2	8
Carb. Adjustment	14	3	4
Carb. Rebuilder ?	20	4	12
Carb. - Springs	18	4	9
Carb. Shop / Supplier	18	4	11
Carb. Supplier	20	1	11
Carb. Supplier / Rebuilder	20	2	22
Carb. Test Stand (Dean Tryon)	28	2	7
Carpet Material - Supplier	23	2	12
Carriage - Pedro II's in Brazil	26	2	1
Caster Angle	14	4	10
Casting Small Parts	9	4	12
Casting Supplier	23	2	7
Chassis Serial Numbers	8	4	11
Chassis Serial Numbers	15	1	11
Chatterer (Current Limiting Relay)	21	1	4 & 5

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

China - Buicks in ...	14	2	5
China - Buicks in ...	14	3	9
China - Wall Plaque	16	4	9
Chile Visit - Donaldson to Grondhuis	19	4	2
Chrome - Imitation	15	4	9
Chrome Plating without Chrome Plating	21	3	7
Cigar Lighter	8	3	15
Cigar Lighter Pictures	9	4	11
Cleaning Tank for Partrts	3	1	10
Cleaning Engine Block	18	3	6
Clock + Bracket, picture + manual	10	4	10
Clock-Pictures & Text	9	1	12
Clock in Rear of Model 50L ?	17	2	11
Clock - Removing From Mirror ?	18	3	12
Clock - Removing From Mirror ?	19	3	12
Clock Glass - Flat or convexed	26	4	10
Clutch	13	2	5
Clutch - Freeing-up After Sitting	21	4	7
Clutch Discs	13	4	11
Clutch Chatter	4	1	9
Clutch Chatter	4	2	10
Clutch Chatter	4	3	8
Clutch Chatter	9	1	10
Clutch Shutter / Grabbing	4	1	9
Clutch Shutter Problem ? (Hatton)	26	3	10
Clutch Chatter Repair	4	3	8
Clutch Chatter Repair Shop	5	2	10
Clutch Cleaning Fluid	4	3	9
Clutch Friction Material Specs	30	2	7
Clutch - Jerking ?	18	4	12
Clutch Problem ?	19	2	12
Clutch Lining	13	3	10
Clutch Problem	12	2	12
Clutch Reassembly	1	4	10
Clutch Rebuild Company	13	1	7
Clutch Rebuilding Supplier	23	2	7
Clutch Rebuilding	14	2	10
Clutch Stuck	9	1	13
Clutch - Stuck / Release	3	3	9
Cold Metal Stitching	17	3	8
Colombia Buicks (Kraus & Cortes Boshell)	25	1	4
Color Combo	8	4	8
Color Combo (20-20)	5	3	9
Color Combo (29-25)	5	4	8
Color Combo (29-26)	6	1	8
Color Combo (29-26s)	6	2	7
Color Combo (29-27)	6	3	6
Color Combo (29-41)	6	4	8
Color Combo (29-44)	7	1	6
Color Combo (29-46)	7	2	4
Color Combo (29-46s)	7	2	5
Color Combo (29-47)	7	3	5
Color Combo (29-48)	7	3	5

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Color Combo (29-49)	7	4	8
Color Combo (29-50)	7	4	9
Color Combo (29-50L)	8	1	7
Color Combo (29-51)	8	1	8
Color Combo (29-54cc)	8	2	7
Color Combo (29-55)	8	2	8
Color Combo (29-57)	8	3	9
Color Combo (29-58)	8	3	10
Color Combo Correction 54CC vs. 50L	11	2	7
Color Combo - Definitions	4	2	7
Color Dupont Numbering System	9	2	7
Colour Combinations from Body #'s ?	18	1	11
Colours - Australian	19	3	6
Commercial Engines (?)	17	2	12
Compression Ratio	12	4	13
Compression Ratio for 29's	12	3	12
Compression Ratio - Increase	9	4	13
Compression (Oct. 5/28 Bulletin)	27	4	10
Condenser Interchangeability	9	4	12
Convertible Rear Window Construction	9	2	10
Convertible Top Material	9	2	10
Convertible Top Repair	10	2	11
Coolant	5	1	8
Coolant	5	3	10
Cooling	8	3	13
Cooling Circulation in 116	3	4	10
Cooling System - Pressurizing ?	15	4	12
Cooling System Tune-up	7	4	13
Cooling System - Pressurizing	16	2	10
Cooling Tune-up 2	7	3	10
Cooling Tune-up 3	7	3	11
Cooling Tune-up 4	8	1	12
Cooling-Tune-up	7	2	8
Cooling Vents (model 25)	5	4	9
Cord (36/37) Listing	26	4	1
Cortes-Boshell, Jorge, Obituary	26	3	1
Cowl Lacing	13	1	7
Cowl Removal ?	16	3	12
Crank Caps	8	1	12
Crank Gear-Fiber Removal	1	2	8
Crank Hole + pictures	11	1	6
Crank Hole Cover	3	1	11
Crank Hole Cover	5	2	11
Crank Hole Cover	5	4	11
Crank Hole Cover	10	3	9
Crank Hole Cover	12	4	11
Crank Hole Cover - 121/129 picture	9	2	11
Crank Hole Cover Pictures	9	1	7
Crankcase Baffles	13	2	5
Dash Molding	9	1	12
Dashboard Color	5	2	11
Dashboard / Instrument Panel Hole	15	1	12
Dashboard Removal - Open Cars	14	3	4

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Dashboards on Right Hand Drive Cars	17	2	10
Dashboard Light Ground	15	3	8
Data Plate (29-50LC) Canadian Export	26	3	8
Dawson Plugs	26	2	9
Dealer Poster - Picture	16	4	10
Dealer Posters - Pictures	19	4	8
Dear Marlene Column	19	4	3
Decal Oil Filter	4	3	11
Decal-Air Cleaner	4	3	11
Decal - Door Molding	5	1	11
Decal - Door Moulding	5	1	11
Decal - New Aust. one	21	2	7
Decal - Door ?	16	3	12
Door Decal - Unusual One	30	1	9
Decal - Oil filter	5	1	10
Decals - Door molding	4	2	9
Decals - Air and Oil Filter - Supplier	19	4	12
Decal Removal from W/S	20	1	6
Deck Lid Restoration	7	1	10
Design and Production Process (Norm McKendry) ?	28	1	12
Designations-Master / Standard	7	2	8
Diagnostic Tests - General (Tryon)	23	2	9
Dickson, Paul - Obit.	29	1	1
Differential Housing Repair	4	4	10
Diff. Oil	22	1	5
Differential Leaks	10	4	13
Differential Vent	22	3	9
Differential - Ratio Change ?	22	3	12
Differential Overhaul (Gunthorpe) Part 1	23	4	6
Differential Overhaul (Gunthorpe) Part 2	24	1	6
Diff. - Master to Std. Swap ?	25	4	11
Distributor Advance - 2 types	12	4	11
Distributor Cap, Rotor, Points	14	3	4
Distributor Ground (Coulombe)	24	4	9
Distributor Lubrication	18	4	8
Distributor - Replacements	22	4	8
Distributor Wires Size	22	4	8
Divider Window Picture + Info 29-50LX	12	1	10
Door Adjustments	23	2	11
Door Edge - paint	3	1	10
Door Handle & Crank Tool	8	2	11
Door Handles - Different Lengths F & R in 55X	24	1	6
Door Handle Repair	9	1	8
Door Handle Repair	20	4	8
Door Handle Repair Tool (Bult)	26	3	8
Door Handle Tool	6	1	10
Door Handle Tool	6	3	12
Door Handle Tool - Ferrule ?	16	4	12
Door Handle - Inner & Crank Repair	6	1	10
Door Handle (Inside) Escutcheon ?	20	1	12
Door Handles Breaking	9	1	7
DoorJamb Colour (Bower)	26	1	10
Door Latch Wood Replacement - ?	15	1	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Door Latch Wood Replacement	15	2	12
Door Latch Hardware ? (Chrome or Nickel)	23	2	12
Door Post Problem (Editor's Car)	19	4	5
Door Scuff Plate / Sill Trim - Supplier	23	4	7
Door Sill ? (Wallace)	27	4	12
Door Striker Plate (Painted or Chrome) ?	24	1	13
Door Striker Plate (Painted or Chrome)	24	2	13
Douma, Peter Obituary	26	1	1
Drive Shaft Tube Removal ?	16	3	12
Duesenberg Fire at Auburn	29	4	2
Dunham, Terry, Obituary	27	1	1
Dust Cover (Axle) Sizes	5	2	11
Dutch Folder (Pictures)	20	2	10
Dutch East Indies 1929 Buick Info Request	21	4	9
Dutch Roadster (Swarttouw) in Family since 1929	30	1	4
Early / Late Info	1	2	6-7
Early / Late Info	3	4	9
Early / Late Info	4	3	10
Early / Late Info	5	1	11
Early / Late Info	8	3	2
Early / Late Info	8	4	9
Early / Late Info	9	1	10
Early / Late Info	9	3	14
Early / Late Info	10	4	8
Early / Late Info	11	1	5
Early / Late Info	8	2	11
Early / Late Differences	3	3	6
Early / Late Fuel Pump Pulsator	5	2	10
Early / Late Radiator Cap	8	3	12
Electrical Conduit "T" Supplier ?	25	1	11
Electrical - Converting to 12 V - ?	15	1	11
Electrical - Converting to 12 V	15	2	11
Electrical Components - Lubrication	10	1	12
Electric Fuel Pump Automatic Shutoff (Bill Bicknell)	30	4	10
Electrical Problem Check-List	17	4	6
Electrical Trouble Shooting	23	2	10
Electrical Wiring - Discussion	19	2	8
Electrical Unit Part Numbers	10	1	13
Electrical Unit Part Numbers	10	1	13
Electrical problem - Cut-out/Headlight ?	19	3	13
Electronic Ignition (Coulombe)	30	4	10
Ellsworth, Terry - Obituary	21	4	1
Engines - Buick in Tractors ?	20	4	12
Engine + Serial Numbers	11	2	7
Engines - Painted Black ? / Info (Problem Engines)	25	1	11
Engine Block Cleaning	22	1	4
Engine Compartment Paint	1	2	8
Engine Compartment Paint	1	4	11
Engine Compartment Paint	2	3	12
Engine Compartment Paint	9	2	9
Engine Compartment Paints	2	4	11
Engine Compartment - paint	2	1	9

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Engine Compartment - paint	3	1	12
Engine Comprerssion - Raised on Standard's	28	1	11
Engine Cooling ?	20	4	11
Engine Colour	5	1	11
Engine - Exterior Cleaning	24	2	8
Engine Green Color # (Datsun)	5	1	10
Engine Paint Colour ?	20	4	11
Engine - Hard to Start ?	16	3	12
Engine Master Part Numbers	13	3	8
Engine Miss	12	4	8
Engine Motor Mount	1	2	8
Engine Number	10	3	9
Engine Number Sequence	9	1	11
Engine Numbers	11	1	9
Engine Numbers	13	1	10
Engine Number Stamped on Head	28	1	6
Engine Oil Additive (ZDDP)	22	2	9
Engine Oil Additive (ZDDP)	22	3	10
Engine Overheating	8	3	13
Engine Overheating	8	4	11
Engine Overheating	9	1	12
Engine Overheating	10	2	11
Engine Overheating	16	4	11
Engine Overheating ?	16	3	12
Engine Overheating - Solving Problem	22	1	7
Engine Painting ? (Before assembly)	20	4	11
Engine Parts Plated - New Zealand	10	2	13
Engine Pic. In Plan	17	3	12
Engine Rebuild Costs (1950's)	11	2	9
Engine Rebuild Cost (Maw)	21	1	6
Engine Replacement Tip	3	3	9
Engine Preparation Guidelines - Pt. 1	17	2	5
Engine Preparation Guidelines - Pt. 2	17	3	6
Engine Replacement / Springs Tip	1	1	4
Engine Rust Solution	5	2	9
Engine - Rear Seals ?	16	3	12
Engine - Rough Running ?	17	4	13
Engine - Freeing up Seized	19	3	7
Engine - Problem Putting Back In	19	4	6
Engine - Problem Putting Back In (Too Long)	30	1	7
Engine - Skips when Idling	18	3	5
Engine Serial #	8	2	12
Engine - Starting First Time	2	2	12
Engine - Starting after Oil Line Clean-out	23	3	7
Engine - Starting 1st Time After Sit.-Pt. 1	17	2	5
Engine - Starting 1st Time After Sit. -Pt. 2	17	3	6
Engine Starting (Start Ya Bastard)	24	2	8
Engine Stuck - What to do	21	4	8
Engine Timing	12	4	8
Engine - Using 28 in 29 ?	15	4	12
Esso Spartan 680 - Inflation	26	4	9
Ethanol Myths Clarified (Mayton)	26	1	8
Exhaust Manifold - Straightening	18	4	8

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Exhaust Manifold - Straightening	19	1	3
Exhaust Ring replacement	11	4	11
Exhaust System Drawing / Info	5	4	9
Exhaust System - Supplier	20	1	11
Exhaust - Heat Shield (Coulombe)	23	2	6
Export Model Designation	8	4	11
Export Models ID	8	3	14
Export X designation	10	4	12
Export X designation	11	1	11
Export - 55 X ?	17	1	11
Factory Pics (Dan Bower) - See Buick Factory Pics			
Fan Belt - as part of Tool Article (Part 2)	2	3	10
Fan Belt - Size	11	4	11
Fan belt - Modern Replacement	12	4	11
Fan Belt - Size	14	3	4
Fan Belt (and Rad. Hose) - Colour ?	24	1	12
Fan Belt (and Rad. Hose) - Colour	24	2	12
Fan Blades 8 vs. 4	9	2	13
Fan Blades, Double	9	1	14
Fan Bracket Removal (Antifreeze)	3	1	10
Fan Pulley Seal	6	4	11
Fan Repair	9	2	12
Fan Repair	18	1	6
Fan Service Tip	10	3	14
Fan Seal	19	1	6
Fan Hub w/Sealed Barings (Tim Wilkinson)	30	4	8
Fender Bolts - Rear	10	4	13
Fender Bolts - Rear	2	1	9
Fender Interchangeability (29 & 30) ?	19	4	13
Fender Kick Plates	3	1	11
Fender Kick Plates	3	2	11
Fender Well Gasket	23	2	8
Fender Welt	13	2	6
Film - "GM Around the World"	23	3	9
Finished Car Packing Slip -	25	2	6
Finished Car Packing Slip - Follow-up	26	2	7
Finland 29-25 discovered in Barn	20	3	1
Fire - Destroys 29-47 (Ray Bean)	23	3	9
Fire - Cause of 29-44 Roadster Fire (McLaughlin)	27	1	7
FireWall Model Plate Repro ?	28	4	9
FireWall Model Plate Reproby Lars Stattin	29	1	7
Firewall Stencil	5	1	5
Firewall - Paint Colour	5	2	11
Firewall - Paint Colour	6	1	13
Firewall - Paint Colour	2	2	11
Firewall - Paint Colour	3	2	6
Firewall - Paint Colour	5	1	10
Firewall - Paint Colour	5	4	11
Finish Car Packing Slip (Michael Robinson's 50)	25	2	6
Fisher Body Plates	9	3	14
Fisher Bros. Movie	29	3	12
Floor Mat	10	4	12
Floor Mats - ?	15	2	12

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Floor Mat - Open Cars	15	1	10
Floor Mat - Supplier	19	2	11
Floor Covering (29-27) ?	29	4	9
Flxible Vehicles - Part 1	17	1	8
Flxible Vehicles - Part 2	17	2	8
Flxible Vehicles - Part 3	17	3	8
Flixable Tow Vehicle Movie (Pathe)	29	3	12
Flxible Bus Photo	30	1	10
Flxible Buick Part Sale	30	2	7
Flywheel Housing Removal	15	1	7
Flywheel Removal ?	17	2	13
Flywheel Removal	17	3	11
Flywheel Removal	17	4	11
Flying Scotsman Rally (2013) Van Gemert	27	4	4
Frame Colour ?	16	3	12
Frame Colour ? (gloss or satin)	20	4	12
Frame - Hidden Number ? (Dunham)	24	3	12
Frame - Painted Number	15	1	11
Frame - Painted Number	15	2	11
Frame - Painted Number on Export Frames	27	4	8
Frame - Painted Number (A.O. Smith Maker)	28	1	12
Frame - Painted Number (George's 27)	29	1	9
Frame - Wood Type	13	1	7
Frame - Wood Type	13	2	6
French, Cliff Obituary	21	3	1
Francisco Auto Heater Signage at Auction	27	1	9
Francisco Auto Heater Info	29	3	12
Front End Shimmy	18	3	5
Front Fender Bracket Types	11	2	14
Front Window Sleeve Repair	8	4	9
Frost Plug Size (Coulombe)	30	1	7
Fuel Delivery Problem ?	21	4	12
Fuel Delivery Solutions	22	1	10
Fuel Gauge Restoration / Filling	14	2	6
Fuel Filter Cleaning	19	4	5
Fuel Problems - By Colin Castle	29	1	4
Fuel Pump Activating Rod Length ?	22	3	9
Fuel Pump - AC Testing Article	26	1	8
Fuel Pump Air Leak	10	3	9
Fuel Pump Bypass with Electric	9	1	9
Fuel Pump Bowl Leak Fix	22	4	8
Fuel Pump Check Valve Problem	12	3	7
Fuel Pump Leak Repair	14	2	9
Fuel Pump Pulsator Shape	4	1	12
Fuel Pump Repair	5	2	9
Fuel Pump Rod Fix	12	4	8
Fuel Pump - Operation/Trouble Shoot	15	3	11
Fuel Pump - Operation/Trouble Shoot	15	4	10
Fuel Pump Pressure ? and Partial Answer	18	3	13
Fuel Pump - Electric Addition	5	2	8
Fuel Pump - Electric	14	3	8
Fuel Pump - Electric Automatic Shut-Off (Bill Bicknell)	30	4	10
Fuel Pump - Low Pressure (from Mac's Auto Parts)	26	1	5

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Fuel Pump - Electric 6 vs. 12 V	20	4	7
Fuel Pump - Electric - Ethanol ?	20	4	11
Fuel Pump - Electric Installation	14	1	8
Fuel Pump - Electric Installation - Correct Method ?	25	1	11
Fuel Pump - Electric Installation	25	2	10
Fuel Pump - Electric Regulator Setting ?	22	2	11
Fuel Pump - Electric Regulator Setting	22	3	11
Fuel Pump - Electric from CarQuest	24	1	11
Fuel Pump - Electric with low pump pressure	24	4	11
Fuel Pump - In Smithsonian Museum	29	4	10
Fuel Pump Problem - Unleaded Fuel	20	3	12
Fuel Pump - Electric in Series	22	4	9
Fuel Pump - Electric in Series	23	1	8
Fuel Pump Interchangeability ?	24	1	13
Fuel Pump Pressure and Gauges	24	3	7
Fuel Pump Rod Length (Standard) ?	27	3	10
Fuel Pump Rod Length - Standard (Blesi)	27	4	12
Fuel - Starvation Problems	20	3	11
Fuel System Set-Up (Lind Coop)	29	3	11
Gas - Diesel Fuel Additive	5	3	10
Gas Additive	19	1	3
Gas Cap Alternative	13	3	9
Gas Cap Pictures	9	1	7
Gas Cap - Locking	11	1	6
Gas Gauge Fluid	2	2	11
Gas Gauge Liquid	3	2	9
Gas Cap - Locking Type	9	1	6
Gas Gauge - Making Work ?	21	1	12
Gas Gauge Restoration	3	2	7
Gas Gauge - Trouble-shooting	14	1	11
Gas Gauge Readings (# of Gals.)	22	2	9
Gas Gauge Rebuild	1	4	10
Gas Gauge Tank Unit / Vapor Lock	18	1	5
Gas Gauge - Fake Liquid	18	4	8
Gas Mileage	6	4	11
Gas Mileage	7	1	11
Gas Tank Filter Grommet	13	2	6
Gas Tank Side Panel	7	2	10
Gas Tank Sending Unit - ?	15	1	13
Gas Tank Repair	14	4	10
Gas-Gasohol	7	2	10
Gas-High test	5	4	10
Gasket - Head - Glue on	20	3	11
Gasket Exhaust, Source	13	3	8
Gasket Listing	7	1	4
Gasket - Marvel Carb Alternative	13	3	8
Gasket - Making Open Car W/S	4	1	7
Gaskets - Listing Part 1	6	3	7
Gaskets - Listing Part 2	6	4	9
Gaskets - Listings Part 1	7	1	4
Gaskets - Listings Part 2	7	2	3
Gaskets - Listings Part 3	7	3	3
Gaskets - Listings Part 4	7	4	6

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Gaskets - Manifold Substitute	21	4	7
Gasket Supplier	22	4	9
Gasket Supplier - Rocker Cover	23	3	7
Gas - Leaded	3	1	12
Gas - Leaded	4	1	13
Gas - Leaded	4	2	8
Gas - Non-Ethanol Locations	25	3	9
Gas - Unleaded	2	1	11
Gas - Unleaded	3	3	9
Gasoline Development I	11	1	7
Gasoline Development II	11	2	6
Gasoline Development III	11	3	4
Gasoline Development IV	11	4	8
Gas Mileage ?	21	2	10
Gasoline - Oxygenated	13	1	9
Gas - Oxygenated	6	4	11
Gas - Regular or high test	6	1	12
Gas - Regular or High Test	5	4	10
Gas Gauge Glass Replacement	20	4	6
Gas Gauge Repair	21	2	6
Gas Gauge Clean Out ?	22	1	10
Gears - Supplier	23	1	8
Gear Box Oil Change	10	2	9
Gear Clashing	9	2	14
Gear Shift Lever Removal	19	1	3
Generator Brushes - Homemade	12	4	7
Generator - Current Relay	5	1	7
Generator - Overcharging	10	2	10
Generator - Tag Picture	10	2	9
German ID Tag	16	4	9
GM's 10,000,000th Car - 1929 Buick	9	1	7
GM's 100th Anniv. / Buick's 105 th	22	3	5
GM's Dealer - Motor Progress Mag.	16	3	9
GM Film - "GM Around the World"	23	3	9
GMC - Buick Powered Truck	14	1	6
GMC - Buick Truck Carb	14	2	5
GMC - Buick Powered Truck - Carb	14	3	8
GMC - 6 Cyl. OHV Engine	15	3	10
Goodyear Blimp - Tow Vehicles	26	4	8
Goodyear - Largest Tire in World	25	2	8
Goodyear Tires on Lafayette, IN Autoshow model 51	28	2	6
Goodyear Tire Test Fleet's 29 Touring Test Car	28	2	9
Golf Club Door Restoration	7	1	10
Golf Club/Rumble Seat Handle	3	1	9
Grease Line Cleaning - ?	15	2	12
Grease Gun (Zerk) Adaptor ?	19	3	12
Grease Gun (Zerk) Adaptor	23	1	8
Grease Gun Type ?	21	1	11
Grease Gun - Operation	21	2	10
Grease Type ?	23	2	12
Halogen Bulbs (Anthony Pearson)	24	1	9
Handles - 26S	3	2	9
Handle (Trunk) on 26 ?	27	1	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Hardware - Stainless (Supplier)	16	4	7
Hardware - Supplier	20	1	11
Head Bolt Tightening Sequence	5	4	9
Head Bolt Tread Repair	6	2	9
Head Bolt Torque Experience	4	3	8
Head Bolt Torque Tool	4	3	8
Head - Engine Number Stamped on Head	28	1	6
Head - High Compression ?	18	1	12
Head - High Compression	10	2	11
Head - High Compression	18	2	11
Head - High Compression - Casting Numbers	28	1	8
Head - High Compression - Gear and Speedo Info	28	1	8
Head - High Comprssion Spark Plugs	28	1	8
Head - Stuck On / Removal ?	18	4	12
Headlight Info (2 types of lens / reflectors)	23	4	9
Headlight Lens Data	16	1	9
Headlight Lens	16	4	10
Headlight Lens Supplier	21	4	7
Headlight Post / Nuts - Different Sizes ?	24	4	13
Headlight Reflector Cleaning	4	3	9
Headlight Reflector Cleaning	15	2	5
Headlight Switch - Repair	20	4	10
Headlight Switch Repair ?	21	1	11
Headlight Certificate (Texas)	29	1	9
Headliner	3	4	11
Hearse (McL-Buick) in BC	26	4	7
Hearse (McL-Buick) in Alberta	28	3	10
Hearse (McL-Buick) - Owned by Emily Reed	30	1	9
Hearse - F.E. Watts Latrobe Australia	30	1	9
Heat Riser Info	2	4	9
Heat Riser Pipe Replacement	2	3	12
Heat Riser Replacement Tube	4	3	9
Heat Riser Teast for Leaks (Green)	27	1	10
Heat Riser Tube Sleeve Material	5	4	10
Heat Riser Tube Replacement Stock	20	2	10
Heat riser - Blocking Off	6	2	10
Heat Riser Heat Exchange Cross Over Tube - Wrap	24	1	6
Heat Riser Heat Exchange Cross Over Tube - Wrap	24	2	8
Heater - Shut-off Valve	10	3	13
Heater - Accessory - Francisco Article	26	1	6
Heater - Accessory - Francisco Signage at Auction	27	1	9
Heater - Accessory - Boverly Article	26	2	7
Helicoil Installation	24	3	9
Hidem Welt Ad	28	2	9
High Speed Running Problem	27	2	10
Hinge Pin Repair	11	4	11
Hinge Pillar (Front) Repair ?	20	2	12
History of Your Car - 1st Mention	24	4	1
Hood - Assembly Repair	6	4	11
Hood - Hot - ?	15	1	12
Hood - Corner Rivet	13	2	6
Hood Corners - Leather not Rubber	5	1	5
Hood Hold Down Repair	9	1	9

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Hood - Hold Down Repair - more	9	2	9
Hood Hold-Up System (Coulombe)	30	2	6
Hood Lacing on Rad Shell ?	29	1	7
Hood Latch Repair	6	4	11
Hood Latch Disassembly	19	1	3
Hood Lift Handle Substitute	3	1	10
Hood Lift Handle Substitution	2	2	11
Hood - Pin Stripe	2	4	9
Hood - Underside Colour	4	4	12
Hood - Underside Colour	5	1	10
Hood - Underside Colour	5	2	11
Horn Tag Picture	10	2	9
Horn Wire - Removing When Stuck	19	4	6
Horsepower Ratings	12	4	2
Hub Cap (Wire Wheel) Hole ?	15	4	12
Hub Cap Removal	7	1	12
Hub Cap sizes	5	2	11
Hub Cap Star Color	3	4	11
Hub Cap Star Color ?	17	2	13
Hub Cap - Painting ?	30	3	9
Hub Color - Paint	8	1	11
Hub Removal - ?	15	2	12
Hub - Rear - Removal	18	2	5
Hubcap - Aftermarket (Pictures)	20	1	8
Hubcap Color	13	1	4
Hubcap Colour ?	17	1	11
Hubcap Colour	17	3	11
Hubcap Colour - Red Inset Colour	23	3	12
Hubcap Pictures	9	4	10,11
Hubcap Types	13	1	5
Hubcap - Holes in Wire Wheel Hubcaps	16	2	10
Hubcap Removal	18	4	7
Hubcap Removal Tool	24	2	8
Hubcap-Rear Mount Disc / Artillery Wheel?	21	3	9
Hubcap - Canadian 2 or 3 Different Models	23	2	7
Hubcap - Early w/ Knurled Edge	23	3	9
Huckster Picture	15	1	5
Ignition Barrel Lock	14	2	12
Ignition Parts (part #'s)	9	1	9
Ignition Lock Removal	14	1	10
Ignition Lock Removal	14	2	11
Ignition Parts	16	1	10
Ignition Switch - Theft Proof	19	4	11
Ignition Swiotch Problem (Shuts off - Jim Boland)	30	4	8
Improvements - 29 vs. 28	18	3	14
Improvements - 29 vs. 28	23	3	11
Index # 1 - Trouble Shooting	7	3	12
Index # 2 - Trouble Shooting	7	4	12
India - 50LX (Madan Mohan Yadav)	28	1	4
India - 49X	28	1	7
Indy 500 29 Buick + picture	10	3	11
Interchangeable 1929 & 1930	7	1	10
Interior Colour Options	15	4	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Interior Kit (57) ?	27	1	11
Introduction Info (Arch Brown Article)	16	1	6
Investment - 1929 Buicks as an Investment	30	1	9
Irishman's Rally - Pics.	19	3	2
Irishman's Rally 2006	21	1	2
Irishman's Rally 2007	21	3	3
Irishman's Rally 2008 - Part 1	22	3	3
Irishman's Rally 2008 - Part 2	22	4	2
Irishman's Rally - Getting Ready for 2011	25	3	3
Irishman's Rally 2015	29	4	5
iWork Format Change - Start	23	2	All
Jansen, Martin - Restoration Story	29	3	2
Job Tags (Standard Finish Form Tags)	27	2	3
Johnston, Dave ? re Model 41 or 51	23	1	9
Johnston, Dave ? re Model 41 or 51	23	2	3
Johnston, Dave re Model 41 or 51	23	3	10
Keys - Ignition Lock (single or double cut ?)	14	2	11
Keys - Ignition Lock (single or double cut)	14	3	7
Keys - Ignition Lock (Key type - B&S)	14	4	9
Keying ?	24	1	12
Keying	24	2	12
Katmandu - Cars to	17	2	11
Kilometer / Speedo	8	3	14
Kilometer / Speedo	8	4	11
Kitchen Store / Motorcycle Shop - Rome	29	2	1
Ladies Toilet Case (French Brochure)	17	2	10
Lap Robe	15	4	9
Lands End - Logo on Golf Shirts (+ 24/1/8)	6	1	6
Latvia - 29-25 Postcard	23	3	9
Leather trim picture	13	2	9
Leatherette for Doors	12	3	13
Lights - Chrome vs. Black Backed	22	1	9
Light Bulb alternative-LED	12	4	6
Light Bulb Supplier	17	3	11
Lights - Driving vs. Passing	19	1	7
Kights - Fender Lights in UK	28	1	6
Lindbergh Kiddnapping	26	2	9
Literature Listings - From ...	2	4	7
Literature Listings - To	5	4	9
Literature - Swedish (Stattin)	25	2	9
Literature - Executive Summary Manual (Landow)	27	4	9
Literature - Canadian Dealer Manual (Bulten)	27	4	9
Logo (Silver Anniversary) on Rear Tire Cover	28	2	6
LSU Engineering Project (Re-Engineering) - Part 1	29	4	10
LSU Engineering Project (Re-Engineering) - Part 2	30	1	8
Lubricants after Engine Rebuild	14	2	10
Lubricant - Transmission, etc. (Mobile)	19	4	6
Lubricant - Transmission, etc. (Shell)	20	1	6
Lubricant - EP Myth	20	4	8
Mohan, Madan Visit (Indian)	28	4	3
Maisonneuve Statue in Mtl. Article	23	4	9
Manifold Repair	11	4	11
Manifold Stud Warpage	12	4	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Manifold Stud Warping	13	1	7
Manuals - On Internet (Mark Shaw)	30	3	9
Marking Parts	15	2	6
Marvel Shirt (Tony Bult)	30	3	10
Marlene's First Article	13	4	3
Marlene's Second Article	15	3	5
Marquette Dealership in Flint, MI	30	2	8
Master / Standard Definitions	5	2	10
McLaughlin Book	10	1	9
McLaughlin Buick Bulletins	16	1	8
McLaughlin Buick's 100th Anniv. Homecoming	22	4	5
McLaughlin Buick Pin	16	1	10
McLaughlin Buick Pin	16	3	2
McLaughlin Carriage Co. Baby Carriage	11	1	12
McLaughlin Dealers-picture July 28 1928	11	4	15
McLaughlin Family Pic's	15	3	9
McLaughlin Family Pic's	16	1	10
McLaughlin - Relationship Bill to RS	3	2	11
McLaughlin, RS (Part 1)	16	2	4
McLaughlin, RS (Part 2)	16	3	5
McLaughlin Trimming Rm. Picture	16	2	8
Metal Tips	13	1	9
Mille Miglia - 1929 - Master 6 engine ?	24	2	13
Mille Miglia 2011 - 1st Part	25	2	1
Mille Miglia 2011 - 2nd Part (Story) Jan vanGemert	25	3	2
Mirror - Sidemount Extensions (Coulombe)	25	2	5
Mirror - Sidemount Extensions (Coul.) Correction	25	3	9
Misc. '29 Buick Tips	1	2	6-8
Misc. Paint/Plating	2	4	9
Model 29-50lx info	12	2	11
Model 48 Introduction	8	4	10
Model 50L Interior Info	12	3	12
Model Description (29-20)	5	3	9
Model 29-20 CC (and maybe 50L CC) - Germany	25	1	5
Model 29-20 CC (and maybe 50L CC) - Germany	25	2	4
Model Description (29-25)	5	4	8
Model Description (29-26)	6	1	9
Model 26 Conversion to 26S ?	20	1	11
Model Description (29-26s)	6	2	7
Model Description (29-27)	6	3	7
Model Description (29-41)	6	4	8
Model Description (29-44)	6	1	6
Model Description (29-46)	7	2	5
Model Description (29-47)	7	3	6
Model Description (29-48)	7	3	6
Model Description (29-49)	7	4	10
Model Description (29-50)	7	4	10
Model Description (29-50L)	8	1	9
Model Description (29-51)	8	1	9
Model Description (29-54cc)	8	2	9
Model Description (29-55)	8	2	9
Model Description (29-57)	8	3	11
Model Description (29-58)	8	3	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Model Differences 121 Vs 129 ?	18	2	12
Models Offered - Australia	19	4	9
Model No. Plate Differences	4	1	12
Model No. Name Plate Repro ?	28	4	9
Model No. on Canadian Export Cars ?	17	2	13
Model No. on Canadian Export Cars	17	3	11
Molasses Dip (Rust Removal)	29	2	7
Motor Mount	1	2	8
Motor Mount- Front Rubber ?	27	1	11
Moulding - Gas Tank Shroud / body	9	2	14
Movie- Wheels of Progress	11	4	10
Movies With '29 Buicks	9	1	2
Movies With '29 Buicks	22	3	10
Movie w/29 Buick in S A	24	1	9
Movie - TV Series "Black-ish"	29	4	10
Moxie Soda's 1929 Buick	30	2	9
Muggy Weld for Cast Iron - Tip	28	3	11
Muffler	13	2	5
Muffler & Front Exhaust - Same 121 & 129	23	3	9
Muffler Specifications ?	18	1	11
Muffler Specifications	18	2	10
Multimeter	25	1	11
Musings - by T. Bult	14	4	8
Musings - by Jack Austin	15	2	9
NAPA - Interrchange Parts (Lowell Lisker)	25	3	11
Nails - Body	6	4	11
Nails - Body	16	4	6
Noyes Buick (Boston) Photo	29	1	10
NZ Billboard (Phil Green)	28	3	1
Odometer Repair	4	1	8
Oil - Synthetics - All Not Equal	22	4	9
Oil Can Holder - Left or Right Side ?	18	1	12
Oil Can Holder - Left or Right Side	18	2	10
Oil Can Holder - Left or Right Side	18	3	12
Oil Can - Is this one Correct ?	24	4	12
Oil Consumption - Valve Guides ?	18	2	12
Oil Consumption - Solution	18	3	11
Oil Capacity	19	4	10
Oil Dip Stick Length ?	20	1	12
Oil Filler Tag Picture	10	2	9
Oil filter	13	3	9
Oil filter	13	4	12
Oil Filter Decal	16	3	9
Oil Filter Length	9	1	13
Oil Filter Length	9	1	12
Oil Filter - Line location	13	4	13
Oil Filter & Lines	14	1	9
Oil Filter Discussion	19	2	8
Oil Lines - at Rocker Arms	18	2	5
Oil Filter - Picture	9	2	11
Oil Filter - Tube Flaring	22	1	8
Oil Leak Reduction (STP)	4	2	8
Oil Leaks - Discussion	19	4	6

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Oil pressure gauge reading solution	12	2	11
Oil Pressure Problems	15	1	12
Oil Pressure Problems	15	2	11
Oil Pressure Problems ?	16	1	12
Oil Pressure Loss (Rt. Hand Corners) ?	20	2	12
Oil Pressure Loss (Rt. H. Crns.) update	20	3	13
Oil Pressure Loss (Rt. H. Crns.) Dealer Bulletin	23	3	10
Oil Pump Gear - Steel vs. Brass ? (Tony Bult)	30	3	9
Oil Pump Screen - Clean it (Shaw)	27	1	7
Oil Pump Wear Repair	6	3	12
Oil Seal - Rear Axle Leak	10	4	13
Oil Smoke Problem	14	4	10
Oil - Type to Use	15	3	8
Oil Smoke Problem	15	1	10
Oil System - Priming Before Starting - 1st Time	23	2	11
Oriental Plus Interiors Ad	18	1	9
Overheating Problems Solving	22	1	7
Overheating Problems Solving - Correction	22	2	7
Over Heating Problem - Parades, etc. (Bill Bicknell)	30	4	8
Owned 29 Longest (Paul Norman / Norm McKendry)	28	2	12
Paint Chips	8	3	9
Paint Color	10	4	7
Paint Color - Dummy Rad. Bottom Strip	9	2	14
Paint Color - Running Gear	9	2	10
Paint Colors	8	4	7
Paint Colors	9	1	5
Paint Colors	10	2	5
Paint Colors	1	2	6-7
Paint Colour - Red for Hubcaps (Buick Vermillion ?)	23	4	12
Paint Colour - Cream	23	4	12
Paint Colour - Fez Red	15	2	13
Paint Colours - Cross Reference ?	18	3	13
Paint Colours - Cross Reference	21	1	8
Paint Colors - Below fender	3	4	10
Paint Engine Compartment	9	3	9,10,11
Paint - Engine Colour	21	4	7
Paint Masking ? (Inside Wheel & Upper Dr. frame)	25	1	11
Paint Masking (Inside Wheel & Upper Dr. frame) - MB	25	2	11
Paint Matching Supplier	23	2	7
Paint Numbering	8	3	14
Paint Numbering	9	3	5
Paint Scheme - 29-27 ?	16	2	10
Paint - Striping on Hood	29	2	11
Paint Stripping	12	4	9
Paint Stripping	12	3	8
Paint Stripping - Molasses Dip	29	2	7
Painting Your Car	4	4	8
Painting - by Mrs. Benoit George	30	3	10
Part Disassembly Made Easy	9	2	12
Parts Suppliers Manual	10	4	14
Parts, Interchangeable with 1930	7	1	11
Parts - Master List for Buick - Info	19	1	6
Part Numbers - Open Car Wood - ?	26	2	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Passenger Comp. - Heat Problem	1	3	5
Pedal car 29 Buick	11	2	9
Pedal Car - Montague Museum	23	4	9
Peking to Paris Report #1	22	3	3
Peking to Paris Report #2	22	4	3
Peking to Paris Report #3	23	1	2
Peking to Paris Report #4	23	2	2
Peking to Paris Report #5	23	3	1
Peking to Paris Report #6	23	4	1
Peking to Paris Report #7	24	1	2
Peking to Paris Report #8	24	2	3
Peking to Paris Report #9	24	3	3
Peking to Paris Report #10 (Actual Rally)	24	4	3
Peking to Paris Report - Post Rally Report	25	1	3
Peking to Paris (2013) Actual Rally Report	27	4	1
Penetrating Oil Comparisons	24	2	11
Penetrating Oil - SP3	29	2	7
Phosporic Acid Solution For Dissolving Rust	29	3	8
Picture 29 Buick	13	2	2
Pictures - 29 Buick	9	3	2,4,5
Pin Striping Pattern	4	4	12
Pin Striping Pattern	5	1	11
Pin Striping	5	2	8
Pin Stripping 1 or 2 ?	21	1	11
Pin Stripping 1 or 2	21	2	9
Pinks - Story of Canada's Oldest McL-Buick Dealer	25	3	5
Pistons - Aluminum Clearances	17	4	11
Piston Rings - Supplier	23	4	8
Point/Cond/Dist Cap From 52 Chevy	5	1	7
Polish Brochures (3) from David Landow	27	1	2
Polish Promotional Piece	28	2	5
Polish State Visit (King Carol II of Romania)	28	2	6
Points - Weak Spring	17	3	7
Portugal Trip ('01)	15	4	2
Poster - Unknown (Yellow car on Blue Background)	25	1	12
Poster - Unknown (Blue - Danish)	25	2	10
Poster - Unknown (Blue - Danish)	26	2	10
Pot Metal Cleaning	23	3	6
Pot Metal Repair Info	21	4	7
Pot Metal Rrpair (Muggy Weld)	28	2	11
Price List - UK	22	4	10
Price Lists (Can. Vs USA)	26	4	7
Production in Germany	12	2	8
Production (When Were they Built)	20	2	5
Production Numbers - 116 Models	2	1	17
Production Numbers - 121 Models	2	2	18
Production Numbers - 129 Models	2	3	18
Production Sequence	8	4	12
Push Rod Cover Gasket	14	2	10
Production Sequence	9	1	11
Pyrolin Lights	8	4	12
Quiz Questions	1	1	5
Quiz Questions	2	2	18

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Radiator Blockage	9	1	14
Radiator Cap	5	4	9
Radiator Cap Customization	4	1	12
Radiator Cap - Optional Picture	14	1	2
Radiator Cap Pictures	8	4	9
Radiator Cap Repair	12	2	10
Radiator Cap Replacement	8	2	10
Radiator Cap - Western Auto picture	9	2	11
Rad. Cap - "Monogram"	17	3	10
Rad. Cap - Monogram (Picture)	20	1	8
Rad. Cap - Aftermarket	23	2	8
Rad. Cap - SS by Enduro Ad	23	4	10
Rad. Cap - Original (Gilmore Museum)	27	4	10
Rad. Drain Extension	20	4	10
Radiator Emblem	1	3	11
Radiator Emblem - Stopped Putting On	2	2	11
Radiator Emblem - Stopped Putting On	4	1	12
Radiator Emblem Color	6	1	13
Radiator Emblem Colour	6	4	12
Radiator Emblem Colour	7	1	11
Radiator Emblem Colour	16	4	11
Radiator Emblem Colour (Finland)	20	3	12
Radiator Emblem Colour (Sweden)	20	4	7
Radiator Decal - Colour ?	16	3	12
Radiator Discharge Problem ? (Clarke)	26	3	10
Radiator Discharge Solution (Clarke)	26	4	10
Radiator Emblem - Different	18	4	11
Radiator Emblem - Different	19	1	9
Radiator Flushing - Washing Soda	16	4	6
Radiator Foaming	13	3	9
Radiator Frothing	4	2	6
Radiator Frothing - Overflow Tank	5	1	8
Radiator Frothing	6	1	12
Radiator Frothing	7	3	11
Radiator Frothing	14	3	5
Radiator Foaming ?	18	4	12
Radiator Frothing ?	25	4	11
Radiator Frothing - Repair Solutions	26	1	9
Radiator Foaming - Water Wetter	19	1	3
Radiator Spewing - Eliminating	27	3	8
Radiator - What's best to use	24	2	11
Radiator - Heat Problem (Todd Smith)	27	3	10
Radiator Hose Filter	22	1	5
Radiator Hose Sizes	11	4	11
Radiator Hose (and Fan Belt) - Colour ?	24	1	12
Radiator Hose (and Fan Belt) - Colour	24	2	12
Radiator Leak Check	7	2	9
Radiator Numbering System	2	3	12
Rad - new (Gary Blesi)	29	2	6
Radiator Overflow System	6	1	12
Radiator Overflow System	5	1	8
Radiator Quick Test	4	2	7
Radiator Repair ?	19	2	12

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Radiator Shell Holes	9	1	14
Radiator Shell Restoration (Mayton)	23	4	10
Radiator Shell - Drilled Holes on Top	9	2	14
Radiator Tag - Canadian	13	2	3
Radiator Thermostat Repair	4	4	10
Radiator - Soldering	7	2	9
Radiator - Master Rad in Standard	9	1	10
Radiator - Master in Standard ?	28	1	12
Radiator - Standard vs. Master	7	1	12
Radiator - Supplier	22	4	9
Radiator Shroud / Splash Pans - Supplier	23	4	8
Radiator - Winterfront (Pines)	25	3	10
Rainbow Chassis	18	2	1
Rainbow Chassis	18	4	10
Rear Bumper (full) Picture	10	1	11
Rear End Bearings	3	3	8
Rear End Master into Standard Swap Response	26	1	9
Rear End - High Speed	11	2	11
Rear Seat Light (picture) - 29-49	12	1	7
Rear Wheel Bearing #'s	3	4	17
Rear Wheel Removal-Stuck	3	4	10
Rear Wheel Felt Seal Installation	18	2	10
Rear Window - Open Car (Picture)	10	1	12
Rear Window (29-25) ?	16	4	12
Rear Window Trim (Closed Car)	17	3	11
Rear Window Trim (Closed Car)	17	4	11
Rear Window - Open Car - Installation	18	3	6
Reference Manual Editions - ?	15	1	11
Reference Manual Editions	15	2	11
Registrations (29 McL-Buick)	28	2	8
Restoration Article - Bill MacKey - From..	1	4	1
Restoration Article - Bill MacKey - To	4	1	6
Restoration Steps / Tips	1	4	7
Restoration Steps / Tips	2	1	7
Restoration Steps / Tips	4	1	6
Restoration Tips	5	2	7
Ribbon - 7th Annual Service Clinic Ribbon	28	1	8
Right Hand Drive Differences	12	2	8
Rim + Lock Rings	9	4	9
Rio Car Club Lunch	29	2	1
Roadster (29-44) Wreck	15	1	9
Robe Rail - Model 57	5	2	11
Robinson, Mike - Winner Pic. - Pg. 1	28	1	1
Rocker Arm Bushing	4	3	9
Rocker Arm - Babbitt Bushing	18	2	5
Rocker Arm Bushing	12	3	13
Rocker Arm Bushing Repair	12	1	12
Rocker Arm Rebuild	3	2	7
Rocker Cover Gasket Material (Supplier)	23	3	7
Rod Bearing Inserts ?	16	4	12
Rods - Removing	20	1	5
Rods - Removing	23	2	9
Roof Material ?	27	1	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Roof Replacement Tip (Seat Belt Material)	23	3	7
Roof Installation	12	1	12
Roof Trim Strip ?	19	2	12
Route 66 w/ Spaniards	29	2	2
Rubber Boots - Shift & Emerg. Brake	22	1	11
Rubber Hose - Proper for Ethnoll Gas	29	4	9
Rumble Seat Latch	8	3	12
Rug Type ?	25	1	11
Rumble Seat Latch	9	1	9
Rumble Seat Lid vs. Trunk ?	16	3	11
Running Board Replacement	10	2	11
Running Board Rubber	12	1	12
Running Board Rubber	12	2	12
Running Board Rubber	12	3	13
Running Board Rubber	12	4	10
Running Board Rubber	13	1	7
Rust Removal on Parts	22	3	9
Rust - Phosporic Acid Solution For Dissolving Rust	29	3	8
Scandinavia Travels (2016) - Part 1 (Lars Stattin's cars)	30	4	4
Seals - Felt and Cork	13	1	10
Seals - Replacement	6	3	12
Seat - Front - Adjustment Gears	19	1	3
Seat Back Cushion Tag	22	2	11
Serial (on frame) Numbers	12	4	6
Serial Numbers	5	1	9
Serial Number Location	8	3	14
Serial Number Location	14	4	10
Serial Number Sequence	9	1	11
Serial Numbers	11	1	9
Serial Numbers	13	1	10
Serial Numbers - New Zealand	17	3	9
Serial Number Plates	3	3	7
Serial Number Tags	3	1	13
Service Report - Model 57	19	4	13
Side-Mount Covers - Metal	19	2	9
Shades / Brackets & Tassels	23	1	8
Sheet Metal Supplier	4	3	9
Shift Rod Heating Dash Fix (Mayton)	27	1	6
Shipping Parts Overseas	9	3	12
Shock Absorber Arm Throw ?	15	4	12
Shock Absorber Rebuilding Service	15	1	12
Shock Absorber Filling ?	15	1	11
Shock Absorber Fluid	13	4	12
Shock Absorber Fluid	14	1	11
Shock Absorber Fluid - Availability	14	2	9
Shock Absorber Lip Seals	15	2	5
Shock Absorber Leaking - Temp. Repair	6	4	11
Shock Absorber Oil	7	3	10
Shock Absorber Rebuild Kit ?	16	1	12
Shock Absorber - Repair (Pt. 1, 2 & 3)	18	4	5
Shock Absorber Rebuilder / Supplier	23	2	7
Shock Rebuilding Guidelines	20	2	7
Shock Shaft Info	20	3	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Shock Absorber Strap	11	2	14
Shock Absorber Strapping	4	2	8
Shock Absorber Strapping	6	4	11
Shock Absorber Strapping	7	1	12
Shock Absorber Bulletin (1927 Canadian)	30	1	7
Shroud Hood Inset (25) ?	23	1	11
Shop / Garage Coat - First Insert	25	1	8
Side Curtain Snaps ?	21	2	11
Side Curtain Rod Insert Sockets ?	21	3	9
Side Curtains - Jaken (Australia)	24	2	10
Side Mount Hardware	3	2	5
Side Mount Metal Covers	23	1	3
Silver Anniversary Reception	10	3	15
Slip-On Body Box	23	4	9
Smoking Cases	23	2	8
South Africa Trip	24	2	5
South American Trip (2008)	22	2	3
Spain (Espana) 29 Buick Club	12	4	13,14
Spanish Rally - 1st Time Attending	12	1	4
Spanish Army Cut-Away 29-27	29	4	4
Spain - Non-Rally (2013)	27	2	5
Spare Tire - Moving Rearward (D. Tryon)	23	1	4
Spare Tire Mounted Behind Trunk	28	2	7
Spark Plug - AC #'s	5	1	7
Spark Plug Fouling ?	22	1	11
Spark Plug Wire	10	2	11
Spark Plug Wires	10	1	12
Spark Plugs	13	4	10
Spark Plugs	14	1	7
Spark Plug Gap - .040 Info / ?	21	4	11
Spark Plug Gap - .040 Usage	22	1	10
Spark - Plug Info / Supplier	18	4	7
Spark Plug - #6 Not Firing Report	20	1	5
Spark Plug Wire Size	22	4	8
Spartan EP 680 - Inflation	17	1	10
Splash Pan colours	14	2	6
Special 29-27	3	4	11
Speedo - Cable Removal at Tranny	19	2	5
Speedo - Cable Removal at Tranny	19	3	11
Speedo Cable - Greasing	21	1	5
Speedo - Connecting ?	22	1	11
Speedo - Driven Gear Count (121/129)	21	1	7
Speedo Driven Gear Casting Differences	28	1	7
Speedo - Electronic	15	2	5
Speedo Gear Removal -Transmission ?	18	1	12
Speedo Gear ?	22	4	11
Speedo Gear to Correct to 3.54 Rear End ? / Answer	30	2	6
Speedo - Only 1 KM (Same for M & S) ?	22	2	11
Speedo / Odometer Repair	4	1	8
Speedo Repair Shops	16	1	10
Speedo Repair Shop / Warning	18	1	10
Speedo Repair - Supplier	19	2	11
Speedo repair - Suppliers	19	3	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Speedo - Operation / Calibration	19	3	8
Speedster (Montana)	26	3	9
Splash Pans / Radiator Shroud - Supplier	23	4	8
Sprague, Brad - Story	20	1	10
Spring Bushings - Front & Rear	3	3	8
Spring Abbreviation Information	4	1	12
Spring Covers / Gators ?	21	1	12
Spring Covers / Gaiters	21	2	10
Spring Repair - Front	5	4	10
Spring Info	3	4	9
Spring - Rear frame to Brake Rod	5	1	7
Spring - Front - Removal	19	1	5
Spring - Oiling (Coulombe)	23	2	6
Sputtering	13	2	7
Standard vs. optional equipment	11	2	5
Standard Finish Form Tags (Job Tags)	27	2	3
Starter Pedal Spring	4	3	9
Starter Plate Standard vs. Master	10	3	10
Starter Tag Picture	9	2	9
Starter / Generator Brush Tension	10	1	13
Starting - Easy (Don Mayton) Shut-off Valve on Carb	30	3	9
Starting Problem	17	1	10
Starting Problem	23	2	10
Starting - Easy with Starter Bolt Modification	29	4	9
Starting Engine - 1st Time After Sit.-Pt. 1	17	2	5
Starting Engine - 1st Time After Sit. -Pt. 2	17	3	6
Steering Adjustment	16	2	11
Steering Box Bearing	5	1	7
Steering Box Leak	3	3	8
Steering Box Lubricant	6	1	11
Steering Box Lubricant	6	4	10
Steering Box Lubricant (STP)	25	3	9
Steering Box - Restoration	7	1	8
Steering Box - Restoration	19	2	6
Steering Box Reconditioning (VG)	20	3	6
Steering Box Repair	20	4	6
Steering Box Repair Tip (Gunthorpe)	26	1	6
Steering Boxes - L and R hand drive	12	3	12
Steering Col. Bracket behind Dash ?	21	2	11
Steering Col. Bracket Difference Lengths ?	22	2	11
Steering Lock (Oakes) Repair - Gunthorpe)	27	3	8
Steering Description / Solutions	12	2	9
Steering - Stiff / Binding repair	11	2	11
Steering Wheel Center - removal ?	17	3	11
Steering Wheel Plastic Refurbishing	22	1	4
Steering Wheel - 116 Plastic Pieces R.	6	2	14
Steering Wheel - 116 Plastic Pieces R.	6	3	13
Steering Wheel Reproduction	16	1	7
Steering Wheel - Wood	20	3	13
Steering Wheel Size ?	23	4	11
Steering Wheel (M&S) Sizes	24	1	11
Stewart, W. F. (Buick Bodies)	16	2	3
Stewart Body Company (Brent Bloede)	23	4	5

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Stewart Body Article - Part 1	26	3	5
Stewart Body Article - Part 2	26	4	4
Stone Guards (Australian)	2	4	10
Storage Tip	7	2	10
Strong / Bennett Correspondence	21	1	7
Sun Visor - on 116 Models	6	2	14
Supplier - Bumper Bolts	24	1	11
Supplier - Brake Lining	25	1	10
Supplier - Carb Floats	25	1	10
Supplier - Carb Rebuilder	25	1	10
Supplier - Chrome Plating (Reasonable - Yackel)	27	4	11
Supplier - Door Scuff Plate / Sill Trim	23	4	7
Supplier - Fuel Pump (A&W Canada)	27	3	8
Supplier - Fuel Gauge Back	29	2	5
Supplier - Fuel Tank Sending Unit	30	4	10
Supplier - Gas Gauge Parts (Glass and Tube)	27	4	10
Supplier - Ignition Parts	29	4	12
Supplier - Light Switch (Steering Col.) Repair	26	4	5
Supplier - Manifold Washers	25	1	10
Supplier - Metal Side Apron	23	4	8
Supplier - Motor Mount (Front) by Tim Wilkinson	29	4	12
Supplier - Obsolete Auto Parts Pty. Ltd. (Australia)	29	4	12
Supplier - Oil w/ZDDP	25	1	10
Supplier - Open Car W/S Frame	24	2	8
Supplier - Open Car W/S Frame	25	1	9
Supplier - Paint	24	4	12
Supplier - Piston & Rings (Egge)	25	1	10
Supplier - Piston Rings	23	4	8
Supplier - Piston Rings	24	1	8
Supplier - Pistons	25	2	5
Supplier - Pistons	29	4	12
Supplier - Splash Apron & Radiator Shroud	23	4	8
Supplier - Seat Springs	24	2	9
Supplier - Speedo Repair	24	4	6
Supplier - Top Hardware	24	4	6
Supplier - Water Pumps	24	4	12
Supplier - Water Pump Rebuilding	24	1	8
Supplier - Water Return Pipe (Czech Rep.)	24	4	12
Supplier - Windshield Rubber Seal between Glass (Bult)	28	3	6
Supplier - Wheel - Wood Respoking	23	2	7
Supplier - Wheels - New Wood Maker	18	3	11
Supplier - Wheel Hub Puller	25	2	5
Supplier - Window Shade Material (Canada)	24	2	12
Switch - Bottom of Steering Column	13	4	8.9
Switch - Electrical Rotary - Different RHD vs. LHD	24	3	7
Swedish King Gustaf's car	22	4	10
Tail Light Bulb Alternative	11	2	11
Tail Light Lens - Paint	13	3	8
Tail Light Lens - Variation	13	2	4
Tail Light Make	8	3	14
Tail Light Make	8	4	11
Tail Light Mounting Info ?	17	3	11
Tail Light - 1930 Minerva	24	2	9

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Tail Light Versions	22	1	11
Tassel Pulls	13	2	6
Temperature Gauge Repair	14	1	8
Temperature Gauge Repair	17	4	11
Temperature Gauge Repair	20	2	7
Temperature Gauge Repair	22	4	9
Temperature Gauge Alternative	13	4	12
Termite Problem ?	17	1	11
Thermostat	12	4	10
Thermostat Alternative	10	3	13
Thermostat - Yes or No	22	4	9
Thermostat Part	7	2	10
Thermostat Repair	4	4	10
Thermostat - Modern replacement ?	26	4	10
Thieves - Targetting Old Car Restoration Shops	30	2	9
Throttle Jamming ?	25	1	11
Throw-out Bearing	9	1	14
Throw-out Bearing Fix	28	1	9
Timing w/ a Buzzer	23	3	6
Timing Gear Problem ?	17	1	11
Timing Gear Problem	17	2	12
Timing Gear Problem	17	3	11
Timing Gear - Number of Teeth - Master vs Standard	29	4	10
Tire Construction	12	3	13
Tire Jack	16	4	10
Tire Problem (Gary Blesi)	29	2	6
Tire Pressure	8	3	12
Tire Pressure	8	2	12
Tire Pump Drawing	3	2	18
Tire - Removal Tool	18	2	4
Tire Replacement on Demountable at Hub (Coulombe)	28	2	10
Tire Size ?	15	4	12
Tire Spreader	10	3	10
Tire Wear	14	2	10
Tire Truing	7	1	11
Tires	12	4	10
Tires - Changing ?	15	4	11
Tire (Rear Spare) Installation	20	2	9
Tires - Removal to Change Tires ?	16	2	11
Tires - Removal to Check Brakes	16	3	10
Tires - Changing	16	1	11
Tires - Changing	16	2	9
Tires - Changing	16	3	11
Tire Changing Without Damaging Rims	19	3	6
Tire Covers ?	16	2	11
Tire Cover (Tryon)	26	3	9
Tire Size ?	17	3	11
Tire Size (Model 25)	4	11	11
Tire - Original Supplier ?	23	2	12
Tire Pressure (Richard Coulombe)	29	3	12
Tires - White walls	8	1	11
Tool - Door handle W/W remover	6	3	12
Tool - Door handle W/W remover	6	1	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Tools - Article - Part # 1	2	2	6
Tools - Article - Part # 2	2	3	7
Tools - Article - Part # 3 - Air Pump	3	2	18
Tools - Article - Part # 4 - Sidemount Removal Bar	3	4	8
Tools - Head Bolt Torque Tool	4	3	8
Tools - info	14	4	7
Tools - Info	15	1	8
Tools - Vlcek Tool Co.	24	2	10
Tools Loaned	7	3	8
Tool Tags	16	1	9
Tool Tag - Photo	16	4	9
Tool Locker in Running Board on UK Models	26	2	6
Top (Hood) Bow Manufacture (Mooney)	27	1	8
Top Irons - Connector ?	16	2	10
Top Irons - Finish ?	16	2	10
Top Moulding	6	1	13
Top Material	17	3	8
Top Material ?	20	4	11
Top Material / Construction ?	21	1	11
Top Material / Construction	21	2	9
Top Rest - Model 44 (picture)	10	1	11
Top Speed	6	2	14
Top Speed - Too Low	6	2	10
Top / Side Curtain Hardware	11	1	13
Top - Tack Strip Material ?	18	3	12
Torque Ball Oil Leak Repair - Part 1	16	4	7
Torque Ball Oil Leak Repair - Part 2	17	1	6
Torque Ball Oil Leak Repair - Part 3	17	2	6
Torque Ball Leaking ?	20	4	12
Torque & Bolt Sizes	5	4	9
Torque Tube - Mating to Gearbox (Wilkinson)	30	2	7
Torques - Stud & General	5	4	10
Torque - Head - Tip	20	3	11
Touring - Spare Parts to bring	4	1	10
Towing	17	3	5
Toy Model ?	26	2	11
Track Inspection Car (Mayton)	25	2	9
Trading Cards - 1st Mention	24	4	11
Transmission Bearings - Front & Rear	3	3	8
Transmission Belting - See Shock Absorber Straps			
Transmission Leak	10	4	13
Transmission Leakage	14	1	10
Transmission Leaks - Stopping	14	3	8
Transmission Lubricant Viscosity in U Joint	11	1	12
Transmission Lub (Chevron Dura-Lith Grease)	22	2	10
Transmission Lub	22	3	9
Transmission - Mating to Torque Tube (Wilkinson)	30	2	7
Transmission Oil	9	1	13
Transmission Oil	13	2	5
Transmission Oil (600W Not Suitable)	22	1	5
Transmission Removal	11	1	12
Transmission Removal	18	1	11
Transmission Seals	3	3	7

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Transmission Shifting / Grinding ?	23	4	12
Transmission Leak ?	19	4	13
Transmission Vent	22	3	9
Transmission Vent Location	23	1	10
Transmission Vent Location	23	2	12
Travel with my 29-44 - To Tony Bult's	29	4	2
Trivia - Quiz Questions	1	1	5-7
Trivia - Quiz Questions	2	2	18
Truck as a 29 Buick - (picture)	10	3	14
Trunk - Building (D. Tryon)	23	1	4
Trunk Rack + pictures	10	3	12
Trunk Rack (picture)	10	2	8
Trunk Rack - Information	20	2	9
Trunk Rack Markings	2	4	7
Trunk Rack Markings	3	1	13
Trunk Rack - Rear Mounted Spare	16	2	6
Trunk Rack - Rear Mounted Spare	20	2	9
Trunk Rack - Extended w/ Buick	17	3	10
Trunk - Wood Treatment / Colour	5	2	12
Trunks + Pictures	10	4	8
Trunk - Lavonia-Luggage	20	1	7
Trunk Rack ? (Difference between Master & Standard)	29	4	9
Tryon, Dean - Story re handle and Ign. Switch	28	1	8
Tune-Up (Car Hard to Start) Info	16	4	11
Tune-Up Info (Vaughn Gunthorpe)	30	3	9
Turarc Disc Wheel Supplier	30	2	8
Turn Signal Wiring Diagram	7	1	8
Turn Signals	7	1	8
Turn Signals	9	1	10
Turn Signals - Add ing Buzzers	27	4	11
UK - Punch Series Ads	19	3	10
UK Dealership (Picture)	20	2	9
UK Price List	22	4	10
UK - Fender Lights	28	1	6
UK Folder	30	1	10
U-Joint Grease Leak	9	2	14
U-Joint - lasted only 300 Miles	18	3	5
Underside of Hood Paint	4	4	12
Underside of Hood Paint	5	1	10
Underside of Hood-paint	5	2	11
Underside of Hood-paint	5	4	11
Upholstery Color	8	3	14
Upholstery / Trim Colors	8	4	11
Upholstery Options ?	15	3	13
Upholstery Patterns ?	17	2	13
Upholstery Project (27) - ?	15	2	12
Upholstery Project (27) - Response	15	3	12
Upholstery- Fabric Supplier	18	4	11
Upholstery Write-Up Challenge	20	1	12
Upholstery - 29-25 ?	20	3	13
Upholstery - 54CC Pleat ? (McKendry)	23	4	12
Unser, Al Jr & 3 (Kent Thomas)	23	3	1
Vacuum W / wiper - Closed Cars	2	1	10

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Vacuum W / wiper - Closed Cars	4	2	10
Vacuum W / wiper rebuild kit	10	2	13
Vacuum Wiper on 29-47 ?	22	1	11
Valve Adjustment Tag - Spanish	13	2	3
Valve Chatter	4	3	11
Valve Cover Tag (picture)	10	2	9
Valve Cover Stamp (Bult)	26	1	8
Valve Cover (Cooking - Raze)	26	4	8
Valve Lash Problem ?	17	1	11
Valve Spring - Compression Test	6	1	9
Valve Spring Length ?	20	1	12
Valve Stem and Cap	8	1	12
Valve Lash When Cold	18	1	11
Valve - replacement Substitute	21	3	7
Valve Timing	19	4	10
Valve Spring Repair Trick	19	4	6
Vapor Lock	1	2	5
Vapor Lock	2	3	13
Vapor Lock	2	4	9
Vapor Lock	2	4	10
Vapor Lock	3	1	10-11
Vapor Lock	3	3	8
Vapor Lock	3	4	11
Vapor Lock	4	2	9
Vapor Lock	4	3	7
Vapor Lock	5	2	11
Vapor Lock - Adding Diesel	5	3	10
Vapor Lock	8	3	11
Vapor Lock	8	4	11
Vapor lock	9	3	14
Vapour Lock ?	26	2	11
Vapor Lock Avoidance (Richard Coulombe)	29	3	12
Vapor Lock Inhibitor - Water Wetter	16	4	6
Vapor lock - Spasmodic	12	3	12
Vapor Lock Theory	9	4	9
Vapor Lock - NOT	10	3	9
Vapor Lock Problem Resolved	20	4	6
Vapor Lock Fix (Return to Tank line)	24	3	7
Vintage & Classic Reproductions - Casting Company	26	4	2
Wandering Car problem ?	17	1	11
Washers - Nord-lock Locking Washers	24	2	9
Watch / Clock	8	4	12
Water Circulation - Standard	2	4	10
Water Pump Color - Standard	3	4	11
Water Pump - Conversion to Take Ceramic Seal (Gunth.)	29	3	9
Water Pump - Gunthorp Conversion - Comment by Blair	30	1	7
Water Pump Grease ?	16	1	12
Water Pump Rebuild Ad	1	3	10
Water Pump - Shaft Repair (14MM)	4	2	8
Water Pump Foaming / Overheating	19	1	4
Water Pump Shaft Movement ?	21	4	12
Water Pump Packing - Supplier	19	4	12
Water Pump Rebuild - Supplier	22	4	9

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX (through Vol. 30 Issue 4)

Water System Filter	22	1	5
Water Return Tube Colour (Bult)	26	1	8
Water Tube Repair - Temporary	5	2	8
Weather Head Fittings - Defined	13	4	10
Weather Head Fittings - Source	13	3	9
Weights of Each Model	23	2	8
Welding - Cold Metal Stitching	17	3	8
Wheel Alignment Specifications	23	2	9
Wheels - Converting to Modern ?	23	1	11
Wheel & Drum Measurement	5	1	11
Wheel Clamps - Standard vs. Master	12	2	12
Wheel Grease	8	1	12
Wheel Grease	22	4	11
Wheel Hub Differences	5	1	10
Wheel - Demount at Rim to Hub Conversion	24	3	11
Wheel Knocker Tool	16	4	11
Wheel Knocker Tool	17	2	12
Wheel - Wire - Lock Ring Drawing	19	1	5
Wheels - New Wood Maker	18	3	11
Wheel Nuts	8	2	12
Wheel Nuts	8	1	12
Wheel - Snap Ring Safety Precaution	24	2	11
Wheel Repair - Wobbly Wheel Repair	3	1	6-8
Wheel Spoke Assembly	3	1	10
Wheel Spoke Bleaching	8	1	10
Wheel Spoke Repair	7	1	12
Wheel Spoke Repair	11	1	13
Wheel Spoke Repair - Part 1	11	2	12
Wheel Spoke Repair - Part 2	11	3	13
Wheel Spokes Stain	13	1	5
Wheel Tread - Front vs. Rear	12	4	13
Wheel - Wood - Color	4	3	8
Wheel - Wood Respoking Supplier	23	2	7
Wheel - Disc Style - Color	3	4	11
Wheel - Disc Supplier (Tuarc)	30	2	8
Wheel - Disc - Rear Spare Tire Mount	30	2	8
Wheel Lugs for Wire and Disc (NAPA)	30	3	10
Wheel - Paint	2	4	10
Wheel - Paint	3	1	13
Wheel - Paint	5	2	11
Wheel - Paint - Hub	3	2	10
Wheel - Wood - Hub Colour	5	2	11
Wheel - Rear - Removal	3	4	10
Wheel - Rear - Felt Seal Installation ?	18	1	11
Wheels - Side Mount Installation ?	24	2	13
Wheels, Split Rim Safety Tip	12	1	9
Wheel - Split Rim Tool - How to Use	20	3	10
Wheels - Paint	3	1	10
Wheels - Pictures	9	3	13,14
Wheel (wood) Rims - New	16	1	7
Wheel - Rim Spreader Tip (Hertzler)	25	2	5
Wheel - Spoke Repair	4	4	10
Wheel - Wood Spoke Repair	1	4	11

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Wheel - Wood Spoke Repair (Douma)	3	1	6
Wheel - Wire spokes	11	3	13
Wheels - Wire - Part #'s	18	1	9
Wheel - Wood discoloration	5	2	8
Wheel - Wire designated "B5" ?	17	3	11
Wheel - Wood Spoke Repair - Part 1	11	2	12
Wheel - Wood Spoke Repair - Part 2	11	3	13
Wheels Meant for Rolling (Spoke Repairs)	22	1	5
Wheels Meant for Rolling (Spoke Repairs)	22	2	7
Wheel - Finishing	22	1	7
Wheel & Pinion Drawing (Standard)	19	3	9
Wind Wings on 54CC ?	24	1	12
Window Winder Handle Repair	6	1	10
Window Decal Picture	10	1	11
Window Ledge Decal Pictures	9	1	7
Window Moulding - Coupe	14	4	9
Window seal 54cc	5	4	11
Window Shades	6	2	9
Window - Curtain	3	1	12
Window - Front Repair	8	4	9
Window - Rear Roadster	3	1	9
Window - Rear Roadster	3	2	9
Window - Rear Roadster Picture	10	1	12
Window - Read on 54CC	5	4	11
Window - Rear	9	2	14
Window - Rear Trim	17	3	11
Window - Rear Frame ?	17	3	11
Window - Rear (Finland)	20	3	12
Window - Rising Problem ?	25	1	12
Window - Rising Problem / Solution	25	2	10
Window Shade Refurbishing	24	2	12
Windshield Disassembly (Closed Car)	5	2	8
Windshield Glass replacement - Touring	4	2	9
Windshield (Front) Removal ?	20	1	12
Windshield Sticker	8	4	12
Windshield Stickers + Picture	9	2	13
Windshield Wiper	12	2	13
Windshield Wiper (48) ?	15	4	11
Windshield Wiper	12	3	13
Windshield Wiper Installation	4	1	9
Windshield Wiper Line Routing	14	2	9
W/S Wiper Vacuum Tubing / Routing	19	1	6
W/S Wiper Vac. Tank w/ Electric Motor	17	4	7
W/S Wiper Blade location-Open Cars ?	15	3	13
W/S Wiper Blade location-Open Cars	15	4	11
W/S Wiper - 54CC - Picture	27	3	10
Windshield - Frame to Body Gasket (Open Car)	4	1	7
Windshield - Touring Replacement	4	2	9
W/S Rubber Replace. (Open Cars) -?	15	1	13
W/S Gasket - (Open Car) Below Glass - Supplier	19	2	11
W/S Rubber (Open Car) Below Glass - Supplier	25	1	8
W/S Rubber (Closed Car) Below Glass (Lisker)	27	4	11
W/S - Wood at Top ?	19	3	12

1929 SILVER ANNIVERSARY BUICK NEWSLETTER - TECH. INDEX
(through Vol. 30 Issue 4)

Windwings On 54CC ?	18	2 & 3	12
Windwing Brackets - Original Accessory ?	26	2	6
Windwings - Accessory	30	4	8
W/S Crank Handle types ?	15	4	12
Witters, Marion Story (VT Roadster)	29	2	11
Winterizing A 29 Buick ?	25	4	11
Wire Wheel Option	13	2	6
Wire Wheel Repair and Painting	21	2	6
Wiring - Steering Wheel Tube	13	2	6
Wiring - Colour coding ?	20	4	12
Wiring "T's" - Replacement	21	3	7
Wood Bows - Open Cars - Painted or Natural ?	22	1	11
Wood - Drawings for 29-55	20	4	5
Wood Type for Bodies - ?	15	2	12
Wood Type for Bodies - ?	21	2	10
Wood Type for Bodies in Canada	6	1	13
Wood Used in USA Bodies	30	4	8
Wood - Steering Wheel	20	3	13
Wrist Pin Supplier	23	2	7
ZDDP Info - See Engine Oil Additive			
<i>Through Dec. 2016 Issue. Thanks to Pieter Korvink for initial completion.</i>			